Properties recommend for removal of Article 4 Direction Control

Lincoln Road (nos. 513-521 odd)
Direction / date of Article 4 Order (No. – 10.12.1981)

	Original features absent at order	■	Original features absent at Review

Lincoln Road	**Windows**				**roof**		**chimney**		**boundary**		**Front door**	
Order: 10.12.81	**bay**		**first**									
513		■		■			**Y**	**Y**		■		■
515		■		■						■		■
517		■		■			**Y**	**Y**				■
519												
521		■		■			**Y**	**Y**				

Original features – 5/5 roofs; 5/5 windows; 5/5 front doors; 3/3 chimneys
Uniform roof – Yes
Apparent historic character - No
Article 4 Direction quality today – No
Number of completely original buildings – 5
Public consultation (1999) - 1 support for deletion

<u>Original windows at first floor 517 removed and replaced since 2011 survey.</u>

Survey 2015

This page is intentionally left blank